	Folknoll
RISK ASSESSMENT RECORD (CONTINUED)	**HS001**
Activity: Working at Height/Using Step Ladders, Ladders & Platforms	**Serial No.:** 001/2007

Likelihood		Severity		Risk Rating		Priority	
1	Insignificant	1	Insignificant harm	1 to 6	Low Risk (Tolerable)	1 to 6	Low priority action (Monitor controls)
2	Unlikely	2	Harmful - Minor injury				
3	Likely	3	Harmful - Lost time injury	8 to 12	Medium Risk (Moderate)	8 to 12	Medium priority action (Reduce the risk)
4	Very likely	4	Harmful - Disabling injury				
5	Almost certain	5	Fatal injury	15 to 25	High Risk (Intolerable)	15 to 25	High priority action (Prohibit work until risk reduced)

Ref. No.	Hazard	Existing Controls	Likelihood	Severity	Risk rating	Priority	Action Required
1	Toppling/Falls from step ladders, ladders & platforms	Permit to work Use of platforms instead of step ladders and ladders where possible Ensure step ladders, ladders and platforms are on level surface Wearing of fall arrest safety harness Wearing of hard hats Training & experience of engineer	1	5	5	Low	Follow requirements of the permit Use correct Ladders/Steps for job Pre-check the area where task is to be performed for slip, trip and fall hazards and remove/minimize Inspect equipment regularly Do not overload Do not overreach
2	Nips & traps of fingers, hands, etc when positioning and using step ladders, ladders & platforms	Ensure step ladders, ladders and platforms are on level surface	2	3	6	Low	Pre-check the area where task is to be performed for nips & trap hazards and remove/minimize Inspect equipment regularly Do not overload Do not overreach