

		<b>Folknoll</b>	
<b>RISK ASSESSMENT RECORD</b>		<b>HS001</b>	
<b>Location:</b> Customer's Site		<b>Serial No.:</b> 001/2007	
<b>Activity (e.g. work task or operation):</b>		<ul style="list-style-type: none"> <li>➤ Working at height during installation of security equipment &amp; systems</li> <li>➤ Using Step Ladders, Ladders &amp; Platforms during installation of security equipment &amp; systems</li> </ul>	
<b>Significant Hazards:</b>		<ul style="list-style-type: none"> <li>➤ Toppling/Falls of step ladders, ladders and platforms</li> <li>➤ Nips &amp; traps of fingers, hands, etc when positioning and using step ladders, ladders &amp; platforms</li> </ul>	
<b>Persons at risk:</b>		Installation Engineer	
<b>Reason (initial, following accident, etc):</b>		Initial	
<b>Key sources of information (Legislation, Approved Codes of Practice, Guidance Notes, etc.)</b>			
<ul style="list-style-type: none"> <li>➤ Working at Height Regulations 2005</li> <li>➤ Safe use of ladders &amp; stepladders IND G 402</li> <li>➤ Provision and Use of Work Equipment Regulations 1998 (PUWER)</li> <li>➤ Lifting Operations and Lifting Equipment Regulations 1998 (LOLER)</li> </ul>			
<b>Actions already taken to reduce risks</b>			
<ul style="list-style-type: none"> <li>➤ Site survey performed prior to commencing work</li> <li>➤ Installation to be undertaken out of office hours</li> <li>➤ See page 2</li> </ul>			
<b>Findings and actions required:</b>			
<b>Findings:</b>		<b>Actions required:</b>	
See page 2		See page 2	
<b>Assessor:</b> Tim Clawson		<b>Date of Assessment:</b> 21 <sup>st</sup> August 2007	
			<b>Page 1 of 2</b>